TRANSMISSION PARTS

Instructions

Hyundai/Kia A5GF1, A5HF1; Mitsubishi F4A41/42/51, F5A51

Oversized Pressure Regulator Valve

Part No. 41954-01K

NOTE: FWD only, replaces OE valves with .540", .616" & .645" spool dia.

Tool Kit

Part No.

F-41954-TL

- Reamer
- Reamer Jig
- Guide Pin

NOTE: Sonnax "F-Tool" kits designed to service a specific bore require the VB-FIX, a self-aligning valve body reaming fixture. More information and instructions can be found online at www.sonnax.com.

NOTE: Required tool kit F-41954-TL is no longer in production.
Check with your distributor for available inventory.





Figure 1

IMPORTANT: The OE valve spool diameters MUST be measured to verify application and therefore which Sonnax oversized pressure regulator valve will replace OE. Proper Sonnax valve and tool kit must be chosen BEFORE reaming the valve body.



*NOTE: Sonnax kit 41954-15K is no longer in production, but may be available from distributor inventory.

1. Disassembly

a. Remove OE retainer and spring adjuster. Save both for reuse.




CAUTION: Do not turn the adjuster screw.

- b. Measure and record OE adjuster setting (Figure 2).
- c. Remove OE spring and pressure regulator valve. Discard valve and keep spring for reuse.

2. Bore Reaming

Ream pressure regulator bore (for reaming instructions/reamer care, please visit www.sonnax.com). Sonnax reaming tool kit **F-41954-TL** and **VB-FIX** are required for this operation.






TRANSMISSION PARTS

OVERSIZED PRESSURE REGULATOR VALVE 41954-01K, F-41954-TL

Instructions

3. Installation & Assembly

- a. Ensure all debris has been removed from valve bore and valve body.
- b. Install Sonnax valve.
- c. Reinstall OE spring.
- d. Before reinstalling OE spring adjuster, verify it is set to the measurement noted during disassembly (**Figure 2**). If that setting is unknown, set the spring adjuster assembly to .250".



e. Reinstall OE spring adjuster and retainer.

4. Final Testing

Vacuum testing at the port(s) indicated holds the recommended minimum 18 in-Hg or more (**Figure 3**).

