TRANSMISSION PARTS

Instructions

Aisin AW TF-60SN; Mini 6F21WA; VW/Audi 09G, 09K, 09M

Oversized K3 Clutch Control Valve Kit

Part No. 15741-59K


- Valve
- Spring

Tool Kit

Part No. F-15741-TL59

- Reamer
- Reamer Jig
- Guide Pin

NOTE: Sonnax "F-Tool" kits designed to service a specific bore require the VB-FIX, a self-aligning valve body reaming fixture. More information and instructions can be found online at www.sonnax.com.



1

CAUTION: Prior to removal of spring adjustment plug, measure and record the distance from the plug to the casting (**Figure 1**). This dimension must be matched during reassembly.

1. Disassembly

- a. Remove and save OE adjustment plug retaining clip.
- b. Measure and record adjustment plug-to-casting distance, then remove and save OE adjustment plug.
- c. Remove OE retaining pin and solenoid, set aside for re-use
- d. Remove and discard OE valve and spring.

2. Bore Reaming

Ream K3 clutch control valve bore (for reaming instructions/reamer care, please visit www.sonnax. com). Sonnax reaming tool kit **F-15741-TL59** and **VB-FIX** are required for this operation.



Location shown may not match your particular application; picture is to illustrate measuring procedure only.



TRANSMISSION PARTS

OVERSIZED K3 CLUTCH CONTROL VALVE KIT 15741-59K, F-15741-TL59

Instructions

3. Installation & Assembly

- a. Be certain all debris has been removed from valve bore and body.
- b. Reinstall OE spring adjustment plug and set to the reference dimension noted in disassembly procedure, then reinstall OE adjustment plug retaining clip.
 - NOTE: To reduce pressure loss past the spring adjustment plug threads, an ATF-compatible thread sealant can be used. Permatex® 24163 surface prep activator combined with blue threadlocker works well for this purpose. Compound used must not create a permanent set.
- c. Install Sonnax spring, followed by Sonnax valve; ensure spring is secured in spring pocket during installation.
- d. Reinstall OE solenoid and retaining pin.

4. Final Testing

Vacuum tests at the ports indicated hold the recommended minimum 18 in-Hg (Figure 2).

