
SONNAX eTM AW55-50SN-ZIP Zip Kit® Available


Critical Wear Areas & Vacuum Test Locations Zip

Drop-In Zip Valve[™] Parts Available

NOTE: OE valves are shown in rest position and should be tested in rest position unless otherwise indicated. Test locations are pointed to with an arrow. Springs are not shown for visual clarity. Low vacuum reading indicates wear and Sonnax parts are noted for replacement.



Middle Control Valve Body • AW55-50SN Shown



sonnax Zip Kit® Available

Critical Wear Areas & Vacuum Test Locations Zip

Drop-In Zip Valve™ Parts Available

NOTE: OE valves are shown in rest position and should be tested in rest position unless otherwise indicated. Test locations are pointed to with an arrow. Springs are not shown for visual clarity. Low vacuum reading indicates wear and Sonnax parts are noted for replacement.

Shift Pressure Control Valve 🔊

• Low Reverse pressure • B1, B2, C2 Clutch burned

Replace with Sonnax Part No. 59947-38K

• 2-3. 3-4. 4-5 Harsh • No 5th

• High line pressure in Reverse

Front View

Rear Control Valve Body AW55-50SN Shown



For specific vacuum test information, refer to individual part instructions included in kits and available at www.sonnax.com.

Click on Sonnax part numbers to see more information.

Shift Pressure Control Plunger Valve

- 2-3 Quality poor
- 3-4, 4-5 Harsh
- High line pressure
- B1. B2. C2 Clutch burned
- Low Reverse pressure

Line Pressure 🛣 **Control (SLT) Accumulator Assembly**

- Low line pressure
- Delayed Forward
- Harsh shifts 2-3 Flare

Replace with Sonnax Part No. 59947-LPC

Side

View

M2 Shift Valve

- No Reverse
- No Neutral control
- No 1st. 2nd. 3rd & 4th

Shift Pressure Relay Valve


- Slips in Reverse
- No engine braking in 2nd. 3rd & 4th

Secondary Regulator Valve

- TCC slip/surge
- Overheated fluid, bushings & converter
- · Poor shift quality
- Harsh Reverse
- Low lube oil flow
- Bushing failure

Replace with Sonnax Part No. 59947-16K

Requires F-59947-TL16 & VB-FIX



Lockup Relay Valve

- TCC apply & release concerns
- Inadequate lubrication
- TCC codes

Replace with Sonnax Part Nos. 59947-01K or

59947-77K Requires F-97741-TL20 & VB-FIX

Seal the port on the opposite side of casting when testing these locations.


Lockup Control Valve % & Sleeve/Plunger Assembly

- TCC apply & release concerns
- Burnt converter TCC codes

Replace with Sonnax Part Nos. 59947-03K or

59947-29K Requires F-59947-TL29. F-15741-TL29PL & VB-FIX

> No. 2 Rear Control Valve Body




©2024 Sonnax Transmission Company, Inc. • A Marmon/Berkshire Hathaway Company




OE Exploded View

Front & Middle Control Valve Body • AW55-50SN Shown

NOTE: Depending upon vehicle application, the OE springs shown may not be present.





Middle Control Valve Body

(Rear side)

Primary Regulator Valve

Solenoid Relay Valve

& Plunger Valve Assembly

& Plunger Valve Assembly

Reverse Shift Ball Check Valve

206


207

208



OE Exploded View

Rear & No. 2 Rear Control Valve Body • AW55-50SN Shown



↑ Rear Control Valve Body Descriptions		
I.D. No.	Description	
301	3rd Gear Band (B4) Control Valve	
302	Shift Pressure Relay Valve	
303	M2 Shift Valve	
304	Shift Pressure Control Valve & Plunger Valve Assembly	
305	Secondary Regulator Valve	
306	Line Pressure Control (SLT) Accumulator	
307	1-2 Reverse Clutch (B5) Control Valve	
308	Lockup Relay Valve & Plunger Valve Assembly	

No. 2 Rear Control		
I.D. No.	Description	
401	Lockup Control Valve & Plunger Valve Assembly	
402	Reverse Shift Restrict Ball Check Valve	
403	2nd Clutch (B2) Control Valve	

