Hyundai/Kia A6GF1, A6LF1/2/3, A6MF1/2



Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

| Communication of Point Toron | Burdana Nama | Don't No | Drop-In ZIP Zip Valve™ Parts | |
|---|--|--------------|--|-----------------|
| Symptoms/Part Type | Product Name | Part No. | Details Zi I Zip Valve [™] Parts | Tooling |
| TCC/Lockup Symptoms | | | | |
| TCC codes, Shudder, TCC apply & release concerns, Excess TCC slip, Overheating | Oversized TCC Control Valve Kit | 1 102741-11K | | F-102741-TL11*‡ |
| TCC codes, Converter shudder & failure, TCC slip, Low TCC apply pressure | TCC Pressure Control Plunger Valve Kit | 2 102741-01K | ZiP | |
| Pressure Problems | | | | |
| Poor shift quality, Soft & inconsistent shift feel, Burnt clutches, Overheating | Oversized Pressure Regulator Valve Kit | 3 102741-08K | | F-102741-TL8*‡ |
| Shift/Engagement Concerns | | | | |
| 1-2 Flare, 5-6 Flare, Ratio codes, Erratic shift timing, 2nd Slip, 6th Slip, No 2nd, No 6th | Oversized 2-6 Pressure Control Valve Kit | 4 102741-16K | | F-102741-TL16*‡ |
| Delayed engagement, Slips, flares & bind-ups, No Forward, No Reverse, Erratic shift timing | Oversized 3/5/Reverse & Underdrive Pressure Control Valve Kit | 5 102741-13K | Fits either of two locations | F-102741-TL13*‡ |
| 3-4 Flare, 4-5-6 Slip, Gear ratio codes, Pressure control out-of-range codes | Oversized Overdrive Pressure Control Valve Kit | 6 102741-18K | | F-102741-TL18*‡ |

^{*} VB-FIX Required

‡ No longer in production. Check with your distributor for availability.

