## GM 5L40-E, 5L50-E



Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

		1	Drop-In	1
Symptoms/Part Type	Product Name	Part No.	<b>Details Z P</b> Zip Valve™ Parts	Tooling
TCC/Lockup Symptoms				
TCC apply & release concerns, Falls out of lockup when hot, No lockup	Oversized TCC Control & Enable Valve Kit	1 55211-22K	Dual-valve pumps	F-55211-TL22**
Code 894, 1870, No lockup, TCC slip, No Reverse, Overheated converter, Harsh TCC apply	TCC Regulator Valve Kit	2 55211-04K	Replaces 0E valves with .511" & .437" dia. valve spools	F-55211-TL4*
Pressure Problems				
2nd Gear starts, Gear ratio codes, Low line pressure, High line pressure, TCC slip, No 4th	AFL Valve Kit	3 55211-01K		F-55211-TL*
High line pressure in Reverse, Low line rise, Gear ratio codes, TCC slip, Flare shifts	Boost Valve Kit	4 55209-04K	ZIP 0E ratio with .474" & .441" dia. valve spools	
	Boost Valve Kit	5 55209-01K	ZiP Performance ratio with .531" & .492" dia. valve spools	
Low pressure, Pump damaged, Pump slide wear, Gear ratio codes, No 4-5	Pressure Regulator Valve Kit	6 55211-08K		55211-TL8
Shift/Engagement Concerns				
1-2 Bind-up, 3-4 Flare, 4-5 Concerns, Clutch distress	Oversized 3-4, 4-5 & Safety Mode Valve Kit	7 55211-14K	Fits any of 3 locations	F-55211-TL14*‡
3-2-1 Bump, Harsh/No engine braking, Clutch failure	Oversized Low Pressure Control Valve Kit	8 55211-17K		F-55211-TL17*
High Performance/Heavy Duty Up	grades			
Upgraded bushing material for long-lasting protection against wear	Bushing	9 77005T	Precision, PTFE-lined	

<sup>\*</sup> VB-FIX Required \*\* VB-FIX & VB-06 Required

	5L40-E Rear Control Valve Body
5L40-E Front Control Valve Body	
SL40 Pump O	D-E Cover

<sup>‡</sup> No longer in production. Check with your distributor for availability.