



Click on part numbers for product details or visit [www.sonnax.com](http://www.sonnax.com) to see all products for the unit(s) shown here.



5R55N Valve Body



5R55N Bell Housing



5R55N Pump



Symptoms/Part Type	Product Name	Part No.	Details	Tooling
<b>TCC/Lockup Symptoms</b>				
Harsh TCC apply, Excess TCC slip, Low line pressure, TCC lining overheat	TCC Back Pressure Spring	1 56947J-S5	5/Bag	
TCC apply concerns, TCC codes, Delayed engagement, Burnt converter	Oversized TCC Back Pressure Valve Kit	2 56947J-63K		F-56947J-TL63*‡
Engine stall, No TCC release, TCC cycling, Burnt converter	TCC Control Valve Spring	3 56947J-S3	5/Bag	
Code P0741, Excess TCC slip, TCC lining failure, Overheated converter, Low cooler flow	Oversized TCC Control Valve Kit	4 56947J-05K		F-56947J-TL2*
Slip codes, High TCC slip RPM at increasing load, Overheated fluid	TCC Modulator Plunger Valve Kit	5 56947J-32K	<b>ZIP</b>	
Harsh TCC apply, TCC slip	TCC Modulator Spring	6 56947J-S4	5/Bag	
Code P0741, Excess TCC slip, Code 1783, High line pressure, Overheated transmission	TCC Modulator Valve Kit	7 56947J-15K		F-56947J-TL15*
<b>Pressure Problems</b>				
Delayed Forward, Delayed Reverse, Low line pressure, High line pressure	Oversized PCA/PCB Modulator Valve Kit	8 56947J-49K	Fits either of 2 locations	F-56947J-TL49*
<b>Shift/Engagement Concerns</b>				
Code 734, 735, Solenoid C Code, No 4th, No 5th	4-3 Pre-Stroke Valve Spring	9 56947J-S1		
Delayed engagement, Burnt Forward clutch	Forward Engagement Control Spring	10 56947J-S6	5/Bag	
Delayed Forward, Loss of Forward, Slipping gears, Burnt Forward clutch	Oversized Forward Engagement Valve Kit	11 56947J-56K		F-27741-TL13*
Delayed engagement, No movement until RPM increased, Pump noise, Low line pressure	Pump Flow Control Valve Kit	12 56200-03K	<b>ZIP</b>	
Delayed Reverse, No Reverse, Direct clutch burned	Oversized Reverse Engagement Valve Kit	13 56947J-59K		F-27741-TL13*
Delayed Reverse, No 4th, No 5th, Direct clutch burned	Oversized Reverse Modulator Valve Kit	14 56947J-53K		F-56947J-TL53*
<b>Component Damage/Failure</b>				
Repeat front seal leakage, Worn pump bushing, Worn converter hub	Bell Housing/Pump Cover Bushing	15 56001X	Finish-in-Place, 5/bag	

\* VB-FIX Required

‡ No longer in production. Check with your distributor for availability.