ZF6HP19/26/32 (Gen. 1) with 053 Separator Plate

sonnax

These parts fit both M-shift and E-shift valve bodies unless otherwise noted.

NOTE: Install spring inboard. ZF6HP19 Valve Body 11 Marian Commission of the Co Fits 11 Locations

Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

0		l 	Drop-In	I
Symptoms/Benefits	Product Name	Part No.	Details Z‡ P Zip Valve™ Parts	Tooling
Multiple Symptoms The first step in correcting common shift problems	Zip Kit®	ZF6-053-ZIP	ZîP	
TCC/Lockup Symptoms				
TCC codes, Excess TCC slip, Cycling RPM, Low TCC release pressure, Flare shifts, Harsh shifts	Oversized Bypass Clutch Control Valve Kit	1 95740-13K		F-95740-TL13*
Excess TCC slip RPM & related codes, Harsh TCC apply & release, Low TCC release pressure	Oversized Converter Release Regulator Valve Kit	95740-05K		F-95740-TL5*
Planetary failure, Bushing failure, Lube failures, Overheating, Low converter pressure	Oversized Lubrication Control Valve Kit	95740-11K		F-95740-TL11*
Pressure Problems				
Broken parts due to excessive line pressure, Erratic line pressure, High line pressure	Pressure Regulator Sleeve	95740-79	ZIP Replaces OE sleeve with .657" outer dia. & .725" length	
Broken parts due to excessive line pressure, Erratic line pressure, Harsh shifts, TCC slip	Oversized Pressure Regulator Valve Kit	5 95740-78K	Replaces OE sleeve with .657" outer dia. & .725" length	F-95740-TL78*
Shift/Engagement Concerns				
Downshift clunk, Firm shifts, Erratic EDS solenoid control and/or EDS codes	Accumulator Piston Kit	6 95740-15K	ZIP Includes 7 pistons & springs	
5-4 Flare, 5-4 Neutral, No 4-5, VFS 1/A solenoid control code, Delayed Forward, Harsh Forward	Clutch A Control Boost Valve Kit	7 95740-21K	ZiP	
Downshift bind-ups, Flare shifts, Excess clutch overlap & clutch distress	Oversized Clutch A Control Valve Kit	95740-09K		F-95740-TL8*
Inconsistent shift quality	O-Ringed End Plug Kit	9 95740-81K	ZIP Includes 1 large & 10 small end plugs	
	O-Ringed Internal End Plug Kit	95740-30K	ZIP Includes 7 end plugs	
Shift concerns, "A" Clutch burned, B Clutch burned, E Clutch burned	Oversized Position Valve Kit	95740-75K	E-shift only	F-95740-TL75*
Flare shifts, Neutral shifts, Harsh upshifts, Harsh downshifts, Gear ratio codes, TCC slip	Oversized Solenoid Pressure Regulator Valve Kit	95740-17K		F-95740-TL17*
Component Damage/Failure				
Lost or damaged component	Converter Release Regulator Valve	95740-05A	ZiP	
		95740-17A	ZiP	
	"Y" Shaped Valve Retainer	95740-04K	10/Bag	
Tools	Solenoid Test Manifold Kit	95430-VTK		VACTEST-01K

^{*} VB-FIX Required

See kit components