


ANY GENERAL APPLICATION



Event: Inductive interference in digital graphing multimeter

Condition: High underhood AC interference

Notes: Can be caused by poor connections, placing SonnaFlow cord over the alternator.