

## TCC Regulator Valve Sleeve

Part No.

**54754-02**

NOTE: 2000-Later, PMW style.

## GM 4L30-E



### 1. Disassembly

- Remove OE retaining pin, saving for reuse.
- Remove OE sleeve and discard.
- Remove OE valve and spring and save for reuse.

### 2. Installation & Assembly

- Be certain all debris has been removed from the pump bore and pump body.
- Install OE spring and valve into Sonnax sleeve.
- Install the sleeve assembly into the pump bore and secure with OE retaining pin.

**NOTE:** Often the OE converter lining has deteriorated. Converter rebuilders may have bonded a new lining to the piston. Some linings are susceptible to TCC cycling or shudder after being rebuilt. We suggest going to a full carbon lining on this type of PWM control.

