


Reverse Boost Valve Kit

Part No.

47740-38K

- Valve
- Sleeve

Toyota/Lexus U760E, U760F



1. Disassembly

- Remove OE retainer and set aside for reuse.
- Remove and discard OE boost valve and sleeve.

2. Installation & Assembly

- Install Sonnax boost valve and sleeve.
- Reinstall OE retainer.

3. Final Testing

Vacuum testing at the port(s) indicated holds the recommended minimum 18 in-Hg.

