## Aisin Seiki AS68RC



## AS68RC Upper Valve Body 5 AS68RC Lower Valve Body

Symptoms/Part Type	Product Name	Part No.	Drop-In ZIP Zip Valve <sup>™</sup> Parts	Tooling
TCC/Lockup Symptoms				
Low cooler flow, Overheated fluid, Internal converter damage	Oversized Cooler Blow-Off Valve	99740-06	3/Bag	99740-TL4
Shift/Engagement Concerns				
Downshift clunk, Flare shifts, Harsh shifts, Shift concerns	Clutch Control Plunger Valve Kit	2 99740-01K	ZIP Dodge only, fits either of 2 locations	
	Clutch Control Valve Spring	<b>3</b> 99740B-01	Mitsubishi & Isuzu only, 2/bag	
Gear ratio codes, Solenoid performance codes, Low solenoid feed pressure, Harsh engagement	Oversized Linear Solenoid Feed Dampener Valve	<b>4</b> 99740-05K	3/Bag	99740-TL4
Solenoid performance codes, Delayed Reverse, Gear ratio codes, 2-3 Flare	Oversized Linear Solenoid Output Dampener Valve	5 99740-04K	2/Bag	99740-TL4
Soft shifts, Flare shifts, Gear ratio codes, Solenoid performance codes, Delayed engagement	Oversized Solenoid Modulating Pressure Blow-Off Valve	6 99740-03	3/Bag	99740-TL4

## www.sonnax.com to see all products for the unit(s) shown here.