Jatco/Nissan RE5R05A

Valve Body

These parts also fit Infinity RE5R05A and Kia A5SR1 and A5SR2.





Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

			Drop-In	
Symptoms/Benefits	Product Name	Part No.	Details Z IP Zip Valve™ Parts	Tooling
TCC/Lockup Symptoms				
TCC codes & concerns, Damaged TCC linings, Lube failures	TC Regulator Valve Kit	1 63741-17K		F-63741-TL13*
Lockup shudder, TCC cycling, TCC codes, Burnt converter, Harsh downshifts, Harsh engagement	TCC Control Valve Kit/Low Brake Switch Boost Valve Kit	2 63741-05K	Z‡P 1st & 2nd Design only	
Lockup shudder, TCC cycling, TCC codes, Burnt converter, Overheating, Poor fuel economy	TCC Control Plunger Valve Kit	2 63741-25K	ZIP 3rd & 4th Design only	
Pressure Problems				
Low solenoid feed pressure, Delayed engagement	Reverse Brake Pressure Control Valve Kit	3 63741-29K	ZiP '09-Later	
Delayed Forward, Harsh Reverse, Erratic line pressure, 2-3 Harsh, Low converter & lube flow	Oversized Pressure Regulator & Boost Valve Kit	4 63741-01K		F-63741-TL*
Shift/Engagement Concerns				
Delayed engagement, Erratic shifts, Flare upshifts & clutch distress, Delayed Forward	"A" or "B" Pilot Valve Kit	5 63741-13K	Fits either of 2 locations	F-63741-TL13*
Component Damage/Failure				
Overheated fluid, Damaged parts & planetaries, Overheated converter, Premature lockup	Oversized Cooler Bypass Valve Kit	6 63741-07K	Not used in all RE5R05A models	F-63741-TL7*

^{*} VB-FIX Required