

Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

Symptoms/Benefits	Product Name	Part No.	Details	Tooling
Pressure Problems				
Burnt clutches, Burnt TCC apply components, Harsh shifts, Soft shifts, TCC codes & concerns	Oversized Supply Pressure Regulator Valve	88740-02	Fits either of 2 locations	F-88740-TL2*
Burnt clutches, Erratic line pressure, Low converter & lube flow, Overheating	Oversized Working Pressure Regulator Valve	2 88740-01		F-88740-TL* ‡

^{*} VB-FIX Required

722.9 Upper

[‡] No longer in production. Check with your distributor for availability.