

1 33740-06

Oversized TCC Apply Valve

Helps cure:

- TCC codes
- Converter shudder & TCC slip
- TCC apply concerns
- Overheated fluid & TCC lining

Note: Requires tool kit **F-33740-TL6** & the **VB-FIX** reaming fixture.




2 33740-03K

Oversized TCC Regulator Valve Kit

Helps cure:

- Converter shudder & TCC slip
- TCC codes
- No lockup
- Overheated fluid & TCC lining

Note: Requires tool kit **F-33740-TL3** & the **VB-FIX** reaming fixture.



3 95740-15K Includes 7 Pistons & Springs

Accumulator Piston Kit

Helps cure:

- Downshift clunk
- Firm shifts
- Erratic EDS solenoid control and/or EDS codes



4 33740-07K

Oversized Forward & Reverse Engagement Latch Valve Kit

Helps cure:

- Code P0811
- Delayed engagement
- Forward slip
- Reverse slip
- Burnt Forward clutch
- Overheating

Note: Requires tool kit **F-33740-TL7** & the **VB-FIX** reaming fixture.



5 33740-01K

Primary Pulley Boost Valve Kit

Helps cure:

- No ratio change
- Ratio codes
- Ratio errors
- No high ratios
- Poor fuel economy

6 33740-04K

Oversized Lube Regulator Valve Kit

Helps cure:

- Bearing failure
- Overheated fluid
- Planetary failure
- Poor lube oil control

Note: Requires tool kit **F-33740-TL4** & the **VB-FIX** reaming fixture.

