Ford AX4N, 4F50N



Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

Symptoms/Benefits	Product Name	Part No.	Drop-In Zip Zip Valve™ Parts	Tooling
Multiple Symptoms				
Comprehensive kit for big problems you don't want back	The Sure Cure® Kit	SC-AX4N		96206-TL‡, 96201-TL2‡, 96201-TL3‡, 96206-BST †‡
TCC/Lockup Symptoms				
Code 628, TCC cycling, TCC surge, No lockup, Lube failures, Excess cooler circuit oil loss	Bypass Clutch Control Plunger Valve Kit	1 96206-03K	ZIP .486" OE large spool dia.	
	Bypass Clutch Control Plunger Valve Kit	1 96206-13K	ZIP .496" OE large spool dia.	
Code P0741, TCC shudder, TCC cycling, Excess TCC slip, TCC apply & release concerns	Oversized Bypass Clutch Control Valve Kit	2 96206-05K		96206-TL‡
Code 628, 741, 744, TCC cycling, Overheating & reduced lube feed, Delayed engagement, No 4th	Oversized Converter Regulator Valve Kit	3 96201-23K	Works in 2- or 4-spooled OE applications	F-96201-TL23
Code 1741, 1744, TCC cycling, No lockup, TCC surge	Oversized Solenoid Regulator Valve Kit	4 96201-21K		96201-TL2‡
Pressure Problems				
Erratic line pressure, Delayed engagement, Pump noise, Pump rotor & cover damage	Oversized Pressure Regulator Valve Kit	5 96206-10K	Late-style	96206-TL2
Pressure loss, Converter drain back	Relief Valve	7 10000-01K	Low radius, 10/bag	
Shift/Engagement Concerns				
1-2 Flare, 2-3 Flare, 2-1 Clunk, Harsh Reverse, Clutch failure, Band failure	Boost Valve Kit	8 96201-01K	ZiP Fits all except 3.0 liter 12 valve, .491" dia. valve, includes 0-rings	
	Boost Valve Kit	8 96201-08K	ZIP Fits all except 3.0 liter 12 valve, .491" dia. valve, factory style sleeve	
	Boost Valve Kit	8 96201-12K	ZIP Fits 3.0 liter 12 valve, .475" dia. valve, includes 0-rings	
Coastdown Neutral after 4th Gear, No Forward, No 4th, Burnt Forward clutch	Forward Control Valve Kit	9 96206-07K	ZiP	96206-BST †‡
Intermittent harsh shifts, 1-2 Soft, 2-3 Soft, Low line rise, Low EPC pressure	Line Pressure Modulator Plunger Valve Kit	10 96948-01K	ZIP AX4N only, .427" valve dia.	
Component Damage/Failure				
Scored shaft	Oil Pump Shaft	11 96855-02K	Patented design increases oil flow	
Lost or damaged component	Pump Shaft Sleeve	12 96201-18		
· .	Pump Slide Pin	13 96200-02	5/Bag	
High Performance/Heavy Duty Up				
Significantly firmer shifts at any gear	Line Pressure Modulator Plunger Valve Kit	14 96948-05K	ZiP AX4N only, extreme heavy duty, .500" dia.	

^{*} VB-FIX Required † Recommended Tool

	7	AX4N Valve Body
6	10 14 1	8
Transmission Reconditioning kit See kit components at MANAY SORDAY COM	11	13

at www.sonnax.com.

[‡] No longer in production. Check with your distributor for availability.