


Honda 4 & 5 Speed, Odyssey, MAXA

POOR & NORMAL



Condition: Poor release oil flow . Proper release oil flow .

Notes: Concerns of high temperature: TCC lining failure; overheat code; TC 740 Code; TCC shudder. Operating temperature high 240-360°F prior to Sonnax converter charge regulated pressure regulator valve 98892-04K. After valve body upgrades - 180°F maximum.