
AXODE



sonnax

Event: After 1-2 shift and between 35-55 mph.

Condition: Misdiagnosed as engine surge.

Correction: Install Sonnax Boost Valve 96201-01K, Bypass Clutch Control Sleeve Kit **96206-01K**, and new valve body relief tees.