


4R44E/5R55E ('99)



Condition: Dotted line is with TCC control valve installed backward.

Notes: Normal TCC apply and flow rate sensitive to pump rpm – set 728 code.