


4L60-E ('94)

sonnax



Condition: Repeated 3-4 clutch failure, 2nd gear starts when hot due to low AFL psi.
Rebuilt bad pump surface to rotor tolerance.

Correction: Needs good pump.