


Toyota /Lexus A750E/F Series

sonnax®

TIME TESTED • INDUSTRY TRUSTED®

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

1 147741-07K Oversized Lockup Relay Valve Kit



Helps cure:

- TCC apply/release concerns & codes
- Burnt converter

Note: Requires tool kit F-147741-TL7 & the VB-FIX reaming fixture.

2 147741-10K Oversized Secondary Pressure Regulator Valve Kit



Helps cure:

- TCC apply/release concerns & codes
- Burnt converter

Note: Requires tool kit F-147741-TL4 & the VB-FIX reaming fixture.

3 147741-01K Boost Valve Kit

Helps cure:

- Low line rise in Drive
- High line pressure in Reverse

4 147741-04K Oversized Main Pressure Regulator & Boost Valve Kit



Helps cure:

- Low/High line pressure
- Soft and/or harsh shifts


Note: Requires tool kit F-147741-TL4 & the VB-FIX reaming fixture.

5 147741-31K O-Ringed End Plug Kit

Helps cure:

- Various concerns depending on location of leaking end plug
- Pressure loss


6 147741-05K Oversized Solenoid Modulator Valve Kit



Helps cure:

- Solenoid performance codes
- Shift concerns

Note: Requires tool kit F-147741-TL5 & the VB-FIX reaming fixture.



These Sonnax kits also are available, see www.sonnax.com for details.



Zip Kit®
A750E-A761E-ZIP



Line Pressure Booster Kit
A750-LB1

7 147741-22K Oversized Clutch Control Valve Kit



Helps cure:

- Harsh up/downshifts
- Flare shifts

Note: Requires tool kit F-147741-TL22 & VB-FIX reaming fixture.


8 147741-37K Lockup Control Plunger Valve Kit

Helps cure:

- Harsh downshifts
- RPM surge on coast

Note: 147741-16K Requires tool kit F-147741-TL16 & the VB-FIX reaming fixture.

9 147741-16K Oversized Lockup Control Valve Kit



10 147741-43K Accumulator Control Plunger Valve Kit

11 147741-24K Oversized Accumulator Control Valve Kit

Helps cure:

- Shift concerns & codes
- Harsh shifts

Note: 147741-24K Requires tool kit 147741-TL24.

12 147741-28K Oversized Brake Control Valve Kit



Helps cure:

- Shift concerns
- Harsh shifts

Note: Requires tool kit F-147741-TL28 & VB-FIX reaming fixture.

13 57917E-19K Accumulator Piston Kit

Helps cure:

- Delayed engagement
- Slips/Flares in Forward gears

14 147741-55K B1 Apply Control Plunger Kit

Helps cure:

- Poor shift quality
- B1 clutch burned