

Toyota/Lexus U341E/F

sonnax®

2 Imtec Lane • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

1 37740-08K Oversized Lockup Control Valve Kit



Helps cure:

- TCC apply & release concerns
- TCC codes
- No lockup
- Converter shudder & slip

Note: Requires tool kit F-37740-TL8 & the VB-FIX reaming fixture.

2 37740-11K Oversized Lockup Relay Valve Kit



Helps cure:

- Inadequate lubrication
- Overheating
- TCC apply & release concerns
- TCC codes

Note: Requires tool kit F-37740-TL11 & the VB-FIX reaming fixture.

3 37740-01K Boost Valve Kit

Helps cure:

- Harsh shifts
- Burnt clutches
- Delayed engagements
- Reverse slip

U341E Upper
Valve Body



U341E Lower
Valve Body

4 37740-03K Oversized Pressure Regulator & Boost Valve Kit



Helps cure:

- Harsh shifts
- Burnt clutches
- Delayed engagements
- Reverse slip

Note: Requires tool kit F-37740-TL3 & the VB-FIX reaming fixture.

5 37740-07K Oversized Secondary Pressure Regulator Valve Kit



Helps cure:

- Harsh TCC apply & release
- Excess TCC slip
- TCC codes
- Erratic TCC apply pressure

Note: Requires tool kit F-37740-TL7 & the VB-FIX reaming fixture.