


TCC Modulator Springs

Part No.
56947J-S4

Springs (5)

Ford 5R55N



1. Disassembly

- Remove OE valve train parts.
- Discard OE TCC modulator spring and keep all other parts for reuse.

2. Installation & Assembly

Install Sonnax spring, then reinstall OE valve train parts and secure with retainer.