


## TCC Back Pressure Springs

Part No.  
**56947J-S5**

Springs (5)

## Ford 5R55N



### 1. Disassembly

- Remove OE valve train parts.
- Discard OE TCC back pressure spring and keep all other parts for reuse.

### 2. Installation & Assembly

Reinstall OE valve train parts, replacing TCC back pressure spring and secure with retaining clip.