

## Lockup Relay Control Valve Kit

### Part No.


**77741-02K**

- Valve
- Sleeve

**NOTE:** For A245E and A246E applications, this part only fits '05-later units with casting code 9132 on the upper valve body.



## Aisin AW 81-40LE; Toyota/Lexus A245E, A246E, A340E, A340F, A650E



### 1. Disassembly

Remove and discard OE lockup relay control sleeve and valve.

### 2. Installation & Assembly

Install Sonnax lockup relay control sleeve and valve assembly as shown.

**NOTE:** No rotational clocking of Sonnax sleeve is necessary.

### 3. Final Testing

Vacuum testing at the port(s) indicated holds the recommended minimum 18 in-Hg.

