


## Pressure Regulator Sleeve

Part No.

**35740-03**

### Chrysler 845RE; ZF8HP45, ZF8HP55, ZF8HP70



#### 1. Disassembly

- Remove OE retainer and keep for reuse.
- Remove and discard OE pressure regulator sleeve.

#### 2. Installation & Assembly

- Install Sonnax pressure regulator sleeve.
- Reinstall OE retainer.

#### 3. Final Testing

Vacuum testing at the outer port holds the recommended minimum 18 in-Hg. Leakage at inboard port is not addressed by this part.

