Instructions

GM 8L45, 8L90

Signal Accumulator Piston Kit

Part No. 154740-06K


- Sleeves (4)
- Pistons (4)
- Springs (4)
- O-Rings (6)

2 Extra

• End Plugs (4)

NOTE: Kit includes 4 piston sets which fit any of 7 locations.

Patent No. 11,933,326



1. Disassembly

Remove and discard OE accumulator pistons and springs.

2. Installation & Assembly

- a. Install Sonnax sleeve into OE casting bore.
- b. Install Sonnax piston into sleeve with open end facing upward.
- c. Install Sonnax spring into piston spring pocket.
- d. Install O-ring into groove in Sonnax plug. Lubricate with Sonnax Slippery Stick **O-LUBE** and roll on bench to size.
- e. Install O-ringed end plug into bore with recessed end upward. The small boss on the end plug should slide into the installed sleeve inner diameter (Figure 1).





TRANSMISSION PARTS

SIGNAL ACCUMULATOR PISTON KIT 154740-06K

3. Final Testing

NOTE: Initial vacuum testing of the OE lineup should utilize the test plate included with the **VACTEST-01K**. For most accurate testing of the installed Sonnax kit, vacuum testing should be conducted by installing a small test tip into the plug hole (**Figure 2**).

Vacuum testing at the port(s) indicated holds the recommended minimum 18 in-Hg (Figure 3).



