


3-4 Accumulator Spring

Part No.

12861-01

Chrysler 42RE, 42RH, 46RE, 46RH, 47RE, 47RH, 48RE



Installation

Install Sonnax spring in place of OE 3-4 accumulator spring.