


GM 10L60/80/90 (Gen. 1 & 2)

These parts also fit Ford 10R60, 10R80, 10R90 and 10R140.

sonnax®

Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.



Symptoms/Benefits	Product Name	Part No.	Details	ZIP Drop-In Zip Valve™ Parts	Tooling
TCC/Lockup Symptoms					
TCC apply & release concerns, Overheated fluid, TCC slip codes	TCC Priority Valve Kit	1 105740-03K	ZIP		
Pressure Problems					
Low line pressure, Various shift concerns, Delayed engagement, Poor shift quality	Main Pressure Regulator Valve Kit	2 105740-12K	ZIP Gen. 1 10L60/80/90, 10R60/80/90/140 only		
	Oversized Main Pressure Regulator Valve Kit	3 105740-20K	Gen. 1 10L60/80/90, 10R60/80/90/140 only		F-105740-TL20*
	Oversized Main Pressure Regulator Valve Kit	3 105740-21K	Gen. 2 10L60/80/90 only		F-105740-TL20*
Component Damage/Failure					
Loss of shift solenoid control pressure, Poor shift quality, Various shift concerns	Solenoid Stabilization Clip Insert	4 105740-01K	ZIP 6/Bag		
	Solenoid Stabilization Retainer	5 105740-19K	ZIP 6/Bag		

* VB-FIX Required