

Click on part numbers for product details or visit www.sonnax.com to see all products for the unit(s) shown here.

Symptoms/Part Type	Product Name	Part No.	Details	Tooling
TCC/Lockup Symptoms				
Erratic TCC apply pressure, Excess TCC slip, Harsh TCC apply & release, TCC codes	Oversized Lubrication Pressure Regulator Valve Kit	1 88740-09K		F-88740-TL9*
Pressure Problems				
Burnt clutches, Burnt TCC apply components, Harsh shifts, Soft shifts, TCC codes & concerns	Oversized Supply Pressure Regulator Valve	2 88740-02	Fits either of 2 locations	F-88740-TL2*
Burnt clutches, Erratic line pressure, Low converter & lube flow, Overheating	Oversized Working Pressure Regulator Valve	3 88740-01		F-88740-TL*
Shift/Engagement Concerns				
4-5 Flare, 4-5 Harsh, Delayed engagement, Harsh engagement	Oversized B2/BR Regulator Valve Kit	4 88740-04K		F-88740-TL4*

* VB-FIX Required

