

Hyundai/Kia A4CF1/2

sonnax®

2 Imtec Lane • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

Click on Sonnax part numbers to see more information.

1 84741-13K Oversized Damper Clutch Control Valve Kit



Helps cure:

- Converter apply/release issues
- Excess slip RPM
- Cycling TCC RPM

Note: Requires tool kit F-84741-TL13* & the VB-FIX reaming fixture.

2 84741-07K TCC Regulator Valve Kit

Helps cure:

- TCC apply/release problems
- Converter codes
- Loss of lube

3 84741-01K Boost Valve Kit

Helps cure:

- Insufficient line rise in drive ranges
- Higher-than-normal reverse pressures
- Soft shifts

4 84741-03K Oversized Pressure Regulator Valve Kit



Helps cure:

- High/Low line pressure
- Soft and/or harsh shifts
- Clutch failure

Note: Requires tool kit 84741-TL3.



5 84741-16K Oversized Pressure Control Valve Kit

Fits Any of 3 Locations



Helps cure:

- Burnt clutches/brakes
- Shift complaints

Note: Requires tool kit F-84741-TL16 & the VB-FIX reaming fixture.

6 84741-10K Pressure Reducing Valve Kit



Helps cure:

- Low line pressure
- No TCC apply
- Delayed forward

Note: Requires tool kit F-84741-TL10 & the VB-FIX reaming fixture.

*NOTE: Tool kit F-84741-TL13 is no longer in production. Check with your distributor for availability.

©2019 Sonnax Transmission Company, Inc. • A Marmon / Berkshire Hathaway Company
The Sonnax products listed here may be protected by one or more patents, or be patent pending.