


4L80-E

GPM/HZ

POOR



Event: TCC applied

Condition: Poor stroke control of TCC regulator valve. Valve does not fully stroke.