
sonnax

G4A-EL FORD ('93 PROBE)



Condition: Weak (bad) pump.

Notes: Large dip as cooler circuit fills, similar to 41TEs (604) with weak pumps.