


45RFE ('01 3.7 JEEP LIBERTY)

sonnax



Condition: Normal. Low flow at low pump revolution and sharp rise on 1-2 shift.

Notes: Cooler return line is lower line on transmission. Increased flow on 1-2 shift identifies operation of VFS solenoid, regulator valve and CC switch valve. Drop in flow of TCC apply notes CC regulator.